

ECO-TESTING

S. No.	Tests	Quantity Required	Test Charges per Sample	
			USD (\$)	EURO (€)
126)	Free Formaldehyde in Textiles ISO: 14184	0.5 m	15	10
127)	Free Formaldehyde in Textiles BS: 6806 Part-2	0.5 m	15	10
128)	Formaldehyde Release in Textiles (AATCC 112-1993)	0.5 m	20	15
129)	Release Formaldehyde in Textiles (BS: 6806:Part: 3, 1987)	0.5 m	20	15
130)	Pentachlorophenol (PCP) Content by GC/ECD	0.5 m	50	40
131)	Organo chlorine / Pesticides Content by GC/ECD	0.5 m	65	45
132)	Arylamines in Azo Dyes by GC/MS	0.5 m	55	40
133)	Heavy Metals by AAS Method			
	✓ Extraction with Perspiration solution (DIN 54020)	0.5 m	70	50
	✓ Copper, Cadmium, Lead, Zinc, Chromium, Cobalt, Nickel (By Flame Photometer) upto ppm level: per element	-	10 [each]	8 [each]
	✓ Mercury and Arsenic (By Hydride Generator) upto ppm level: per element	-	15 [each]	12 [each]
	✓ Copper, Cadmium, Lead, Zinc, Chromium, Cobalt, Nickel (By Graphite Furnace) upto ppb level: per element	-	15 [each]	12 [each]
134)	Polychlorinated biphenyls	50 g	70	50
135)	Thin Layer Chromatography	50 g	30	20
136)	Analysis of Organic Compounds by GC-MS	50 g	65	55
137)	HPLC Analysis	50 g	30	20