

Standard Test Methods for the Nonwovens and Related Industries



Worldwide Strategic Partners



E D I T I O N 2 0 0 8

Standard Test Methods for the Nonwovens and Related Industries

Table of Contents

Description	Method Number	Equivalent Methods	ISO Reference	Page Number
1) GUIDANCE DOCUMENTS	WSP	<u>IST/ERT REFERENCE</u>	<u>ISO EQUIVALENT</u>	PAGE
Glossary of Terms	WSP 1.0 (05)	-		
How to Write a Test Method	WSP 2.0 (05)	-		
Sample and Laboratory Conditioning	WSP 3.0 (05)	ERT 60.2 (99)		
Worldwide Associations	WSP 4.0 (05)	ERT Useful Addresses		
Sampling	WSP 5.0 (05)	ERT 130.2 (99)		
List of Vendors	WSP 6.0 (05)	Useful Vendor's List		
Guidance to Nonwoven Test Methods	WSP 7.0 (05)	INDA Guidance Document		
Guidance to Highloft Test Methods	WSP 8.0 (05)	INDA Guidance Document		
2) ABSORPTION				
Nonwoven Absorption	WSP 10.1 (07)	ERT 10.4 (02)	9073 - 6:2000	
Rate of Sorption of Wiping Materials	WSP 10.2 (07)	IST 10.2 (01)		
Demand Absorbency	WSP 10.3 (07)	ERT 230 1 (02)	9073 – 12-:2002	
Evaluation of oil and Fatty Liquids Absorption	WSP 10.4 (08)	EDANA New Method		
3) ABRASION RESISTANCE				
Inflated Diaphragm	WSP 20.1 (07)	Modified IST 20.1 (01)		
Flexing and Abrasion	WSP 20.2 (07)	Modified IST 20.2 (01)		
Double Rotary Platform (Tabor)	WSP 20.4 (07)	Modified IST 20.4 (01)		
Modified Martindale	WSP 20.5 (07)	Modified IST 20.5 (01)		



Standard Test Methods for the Nonwovens and Related Industries

Table of Contents

Description	Method Number	Equivalent Methods	ISO Reference	Page Number
<u>4) BURSTING STRENGTH</u>				
Diaphragm Burst	WSP 30.1 (07)	Modified IST 30.1 (01)		
Burst	WSP 30.2 (07)	ERT 80.4 (02)		
<u>5) ELECTROSTATIC PROPERTIES</u>				
Surface Resistivity	WSP 40.1 (07)	IST 40.1 (01)		
Decay	WSP 40.2 (07)	IST 40.2 (01)		
<u>6) OPTICAL PROPERTIES</u>				
Opacity (INDA)	WSP 60.1 (07)	IST 60.1 (01)		
Brightness (INDA)	WSP 60.2 (07)	IST 60.2 (01)		
Brightness (EDANA)	WSP 60.3 (07)	ERT 100.1 (78)		
Opacity (EDANA)	WSP 60.4 (07)	ERT 110.1 (78)		
<u>7) PERMEABILITY</u>				
Air Permeability	WSP 70.1 (07)	Modified IST 70.1 (01)	9073 – 15:2007	
Liquid Strike-Through	WSP 70.3 (07)	ERT 150.5 (02)	9073 – 8:1995	
Water Vapor Transmission Rate Mocon/INDA	WSP 70.4 (07)	IST 70.4 (01)		
Water Vapor Transmission Rate Mocon/EDANA, Part 1	WSP 70.5 (07)	-		
Water Vapor Transmission Rate Lyssy/EDANA, Part 2	WSP 70.6	-		
Repeated Liquid Strike-Through Time	WSP 70.7	ERT 153.0:(02)	9073 – 13:2006	

Standard Test Methods for the Nonwovens and Related Industries

Table of Contents

Description	Method Number	Equivalent Methods	ISO Reference	Page Number
Wetback after Repeated Strike-Through	WSP 70.8	ERT 154.0 (02)	9073 – 14:2006	
8) REPELLENCY				
Surface Wetting Spray	WSP 80.1 (05)	IST 80.1 (01)		
Penetration by Water (Rain Test)	WSP 80.2 (05)	IST 80.2 (01)		
Penetration by Water (Spray Impact)	WSP 80.3 (05)	Modified IST 80.2 (01)	9073 – 17:2008	
Penetration by Saline Solution (Automated Mason Jar)	WSP 80.5 (05)	IST 80.5 (01)		
Water Resistance (Hydrostatic Pressure)	WSP 80.6 (05)	IST 80.6 (01)/IST 80.4 (01)	9073 – 16:2007	
Penetration by Oil(Hydrocarbon Resistance)	WSP 80.7 (05)	IST 80.7 (01)		
Alcohol Repellency	WSP 80.8 (05)	IST 80.8 (01)		
Run-Off	WSP 80.9 (05)	ERT 152.2 (02)	9073 – 11:2002	
Coverstock Wetback	WSP 80.10 (05)	ERT 151.3 (02)		
Wet Barrier Mason Jar	WSP 80.11 (05)	ERT 170.1 (02)		
9) STIFFNESS				
Cantilever Bending (INDA)	WSP 90.1 (05)	Modified IST 90.1 (01)		
Stiffness Using the Gurley	WSP 90.2 (05)	Modified IST 90.2 (01)	9073 – 7:1995	
Handle-O-Meter	WSP 90.3 (05)	Modified IST 90.3 (01)		
Cusick Drape	WSP 90.4 (05)	ERT 90.4 (99)	9073 – 9:1995	
Bending Length (EDANA)	WSP 90.5 (05)	ERT 50.5.(99)		



Standard Test Methods for the Nonwovens and Related Industries

Table of Contents

Description	Method Number	Equivalent Methods	ISO Reference	Page Number
10) TEAR STRENGTH				
Elmendorf	WSP 100.1 (05)	Modified IST 100.1 (01)		
Trapezoid Tear	WSP 100.2 (05)	IST 110.2 (01)/ ERT 70.4 (99)	9073 – 4:2008	
Tongue Tear	WSP 100.3 (05)	Modified IST 100.3 (01)		
11) TENSILE				
Grab Tensile	WSP 110.1 (05)	Modified IST 110.1 (01)	9073 – 18:2007	
Strip Tensile	WSP 110.4 (05)	IST 110.5 (02)/ERT 20.2 (89)	9073 – 3:1989	
Ball Burst	WSP 110.5 (05)	-	ISO/DIS 9073 – 5	
12) THICKNESS				
Thickness (INDA)	WSP 120.1 (05)	Modified IST 120.1 (01)		
Thickness of Highloft	WSP 120.2 (05)	Modified IST 120.2 (01)		
Compression and Recovery, Highloft	WSP 120.3 (05)	IST 120.3 (01)		
Compression and Recovery, Highloft Using Weights and Plates	WSP 120.4 (05)	IST 120.4 (01)		
Compression and Recovery, Highloft High Temperature/High Humidity	WSP 120.5 (05)	IST 120.5 (01)		
Thickness (EDANA)	WSP 120.6 (05)	ERT 30.5 (99)	9073 – 2:1995	
13) WEIGHT				
Mass per Unit Area	WSP 130.1 (05)	ERT 40.3 (90)	9073 – 1:1989	
14) BINDER/APPEARANCE/DRYCLEANING				

Standard Test Methods for the Nonwovens and Related Industries

Table of Contents

Description	Method Number	Equivalent Methods	ISO Reference	Page Number
Binder Distribution/Penetration	WSP 150.1 (05)	IST 50.1 (01)		
Appearance and Integrity of Highloft Batting	WSP 150.2 (05)	IST 50.2 (01)		
15) LINTING				
Particulate Shedding, Dry	WSP 160.1 (05)	IST 160.1 (01)/ERT 220.1(02)	9073 – 10:2003	
Particulate Shedding, Wet	WSP 160.2 (05)	IST 160.2 (01)		
Fibrous Debris from Nonwovens	WSP 160.3 (05)	IST 160.3 (01)		
Fibrous Debris from Hydrophobic Nonwovens	WSP 160.4 (05)	IDT 160 4 (01)		
16) SUPERABSORBENT MATERIALS				
pH of Polyacrylate (PA) Powders	WSP 200.2 (05)	ERT 400.2 (02)/IST 200.1(02)	17190 – 1:2001	
Residual Monomers	WSP 210.2 (05)	ERT 410.2 (02)/IST 210.2(02)	17190 – 2:2001	
Particle Size Distribution	WSP 220.2 (05)	ERT 420.2. (02)/IST 220.0(02)	17190 – 3:2001	
Mass Loss Upon Heating	WSP 230.2 (05)	ERT 430. 2 (02)IST 230.0(02)	17190 – 4:2001	
Free Swell Capacity in Saline, Gravimetric Determination	WSP 240.2 (05)	ERT 440 2 (02)IST 240.2(02)	17190 – 5:2001	
Fluid Retention Capacity in Saline, After Centrifugation	WSP 241.2 (05)	ERT 441.2 (02)/IST 241.2(02)	17190 – 6:2001	
Absorption Under Pressure, Gravimetric Determination	WSP 242.2 (05)	ERT 442.2 (02)/IST 242.2(02)	17190 – 7:2001	

Standard Test Methods for the Nonwovens and Related Industries

Table of Contents

Description	Method Number	Equivalent Methods	ISO Reference	Page Number
Flow-rate, Gravimetric Determination	WSP 250.2 (05)	ERT 450.2 (02)/IST 250.0(02)	17190 – 8:2001	
Density, Gravimetric Determination	WSP 260.2 (05)	ERT 460.2 (02)/IST260.2(02)	17190 – 9:2001	
Extractable	WSP 270.2 (05)	ERT 470.2 (02)/IST 270.2(02)	17190 – 10:2001	
Respirable Particles	WSP 280.2 (05)	ERT 480.2 (02)/IST 280.2(02)	17190 – 11:2001	
Dust in Collection, Sodium Atomic Absorption/Emission Spectrometry	WSP 290.2 (05)	ERT 490.2 (02)/IST 290.2(02)		
17) BACTERIAL			17190 – 12:2002	
Filtration Efficiency	WSP 300.0 (05)	ERT 180.0.(89)		
Dry Bacterial Penetration	WSP 301.0 (05)	ERT 190.1 (02)		
Wet Bacterial Penetration	WSP 302.0 (05)	ERT 200.1 (02)		
18) FORMALDEHYDE				
Water Extraction Method I	WSP 310.1 (05)	ERT 210.1 (99)		
Stressed Extraction Method II	WSP 311.0 (05)	ERT 211.1 (99)		
Free Formaldehyde Determination HPLC, Method III	WSP 312.0 (05)	ERT 212.0 (96)		
Free Formaldehyde in Processing Method IV	WSP 313.0 (05)	ERT 213.0.(99)		
20) ABSORBENT HYGIENE PRODUCTS				
Syngina Method (Tampons)	WSP 350.1 (05)	ERT 350.0 (02)		
Ethanol – Extractable Organotin 1	WSP 351.0 (05)	ERT 360 0 (02)		
Synthetic Urine – Extractable Organotin II	WSP 352.0 (05)	ERT 361. 0 (02)		



Standard Test Methods for the Nonwovens and Related Industries

Table of Contents

Description	Method Number	Equivalent Methods	ISO Reference	Page Number
Absorption Before Leakage using an Adult Mannequin	WSP 354.0 (08)	EDANA New Method		
<u>21) USEFUL METHODS</u>				
Surface Linting	WSP 400.0 (05)	-		
Lamination Strength	WSP 401.0 (05)	-		
<u>22) Fiber glass mats</u>				
Sampling and Lot Acceptance	WSP 600.0 (08)	TAPPI T-1006		
Sample Location for Fiber Glass Mat Sheets	WSP 601.0 (08)	TAPPI T-1007		
Test Conditions for Fiber Glass Mat	WSP 602.0 (08)	TAPPI T-1008		
Tensile Strength and Elongation at Break	WSP 603.0 (08)	TAPPI T-494		
Basis Weight	WSP 604.0 (08)	TAPPI T-410		
Moisture Content	WSP 605.0 (08)	TAPPI T-1012		
Loss on Ignition of Fiber Glass Mat	WSP 606.0 (08)	TAPPI T-1013		
Moisture Sensitivity of Fiber Glass Mat	WSP 607.0 (08)	TAPPI T-1014		
Uniformity of Fiber Glass Mats	WSP 608.0 (08)	TAPPI T-1015		
Average Fiber Diameter of Fiber Glass Mats	WSP 609.0 (08)	TAPPI T-1016		